

Cochiti Campground Renovation



Recreational facilities include campsites, electrical hookups, picnic sites, group shelters, restrooms, showers, drinking water and dump stations. Despite annual maintenance since their completion, these facilities have slowly become outdated and too small for the needs of the area. New guidelines and building codes have been implemented which make these facilities outdated and unsafe. This is especially true of facilities on the west side of the lake. A campground design is in-progress.